

# XPRO.20 SPRAYER™

PRO Power, XTREME Coverage

**COVER PLATE MUST BE IN PLACE WHILE OPERATING SPRAYER!**

## REPAIR PARTS



**PN: 69113**  
REPLACEMENT PUMP



**PN: 69114**  
REPLACEMENT LiFePO4 BATTERY



**PN: 01145**  
LiFePO4 BATTERY CHARGER



**PN: 01147**  
POWER CONTROL



**PN: 01153**  
5 AMP CIRCUIT BREAKER



**PN: 61009**  
VITON O-RING FOR WAND/GUN



**PN: 01141**  
VITON O-RING FOR BRASS QC



**PN: 01148**  
RUBBER FOOT



**PN: 65350**  
0.10 GPM BRASS FAN TIP



**PN: 65310**  
0.50 GPM BRASS FAN TIP



**PN: 66401**  
BRASS SPRAY GUN W/QC END



**PN: 64300**  
12 IN. STRAIGHT BRASS WAND



**PN: 64310**  
12 IN. CURVED BRASS WAND



**PN: 69115**  
REPLACEMENT SUCTION HOSE





**PN: 69109**  
25 FT. HOSE KIT

## BATTERY

## TO OPTIMIZE BATTERY PERFORMANCE

- CHARGE YOUR BATTERY PRIOR TO INITIAL USE and CHARGE PRIOR TO STORAGE
- AVOID DISCHARGING BATTERY TO EMPTY
- CHARGE ONLY WITH FACTORY APPROVED CHARGER
- AVOID DROPPING OR CRUSHING
- OPTIMAL TEMPERATURE RANGE -20° F TO 120° F

## WIRING DIAGRAM



Depress orange button to release or install wire.



### WARNING FOR CALIFORNIA CUSTOMERS:

Cancer and Reproductive Harm - [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov)

NOT FOR USE WITH FLAMMABLES!